

TEST REPORT

No.: SZML190951856

Date: Oct. 12, 2019 Page: 1 of 3

NOVAL GLASS GROUP LTD

NO.33 SHANDONGROAD, QINGDAO CHINA

The following sample(s) was/ were submitted and identified on behalf of the client as:

Sample Name : SECOND-GENERATION COPPER FREE MIRROR

SGS Ref No. : GZMR190916323

Sample Information : PRODUCT COLOR: LIGHT GREEN Test Performed : Selected test(s) as requested by applicant

Date of Receipt : Sep. 30, 2019

Test Period : Sep. 30, 2019 to Oct. 11, 2019

Test result(s) : Please refer to the following page(s)

*******To be continued******

Signed for and on behalf of

Ramber Li Authorized Signatory



TEST REPORT

No.: SZML190951856

Date: Oct. 12, 2019 Page: 2 of 3

Test Information:

Sample description: See photo

Test item: Copper-Accelerated Acetic Acid-salt Spray Test

Test method: ISO 9227: 2012 (CASS)

Test conditions:

CASS solution makeup: (50±5)q/L NaCl + (0.26±0.02)q/L CuCl₂·2H₂O

Chamber temperature: (50±2)℃

Volume of salt solution collected: (1.0~2.0) ml/(80cm2-h)

pH of collected solution at (25±2) °C: 3.1~3.3

Exposure period: 120h

Test result(s):

Sample		Appearance		
		#1	#2	#3
1	"Obverse" (coating side)	Visible discoloring	No visible change	No visible change
	"Inverse" (glass side)	No visible change	No visible change	No visible change

Note: The above test was carried out by a SGS laboratory.




TEST REPORT

No. : SZML190951856

Date: Oct. 12, 2019

Page: 3 of 3

Photos:



The document of a seaded by the Company analyst or to Marketin Conditions of Section protect of Vision and American Conditions of Section protection and Implication and Conditions of Section and Conditions and Condit